


LS-9100 Configuration sheet


1. Set All Defaults



2. Do Not Transmit UPC-A Check Digit



3. Do Not Transmit UPC-E Check Digit



LS-9100


Configuration sheet

(Continued)

4. Scan Options



5. <DATA> <SUFFIX>



6. Enter

